

**PRODUCT SECURITY PATCH LIST
FOR
ANGIO WORKSTATION
(2G984-0027EN)**

CANON MEDICAL SYSTEMS CORPORATION

Trademarks

Windows® is a registered trademark of Microsoft Corporation in the United States and other countries.

This document may also include trademarks or registered trademarks of other companies.

Note that the trademark symbol "™" and the registered trademark symbol "®" may or may not be used in this document.

IMPORTANT!

1. No part of this document may be copied or reprinted, in whole or in part, without written permission.
2. The contents of this document are subject to change without prior notice and without legal obligation.
3. The contents of this document are correct to the best of our knowledge. Please inform us of any ambiguous or erroneous descriptions, missing information, etc.

REVISION RECORD					
REV.	DATE (YYYY-MM)	REASON	PAGE CHANGED	SER. No.	DOC. PRODUCT.
INI.	2025-02		-----		NASU

Security Patch Package name

SPZX17-20085_202501VL_AWS93_hotfix_win10_LTSC2019_x64_enu

Applicable Products for the Security Patch

XIDF-AWS801/B3	V9.0 SP0006*- V9.0 SP0xxx*
	V9.2 SP0005*- V9.2 SP0xxx*
XIDF-AWS801/B4	V9.3 SP0xxx*-
	V9.5 SP0xxx*-

Steps to Apply the Security Patch

Please follow the instruction of applying patches defined by each of the product Security Patch Package. For details, please contact the customer service for each system.

Verified Security Patch List

KB	MSRC	explanation(en-us)	URL/File Name	url
KB5005112	n/a	2021-08 Servicing Stack Update for Windows 10 Version 1809 for x64-based Systems (KB5005112)	windows10.0-kb5005112-x64_81d09dc6978520e1a6d44b3b15567667f83eba2c.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2021/08/windows10.0-kb5005112-x64_81d09dc6978520e1a6d44b3b15567667f83eba2c.msu
KB5050008	n/a	2025-01 Cumulative Update for Windows 10 Version 1809 for x64-based Systems (KB5050008)	windows10.0-kb5050008-x64_80eb33a0afcef07b95b6d5925b174e6a189bb6c9.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2025/01/windows10.0-kb5050008-x64_80eb33a0afcef07b95b6d5925b174e6a189bb6c9.msu
KB5049615	n/a	2025-01 Cumulative Update for .NET Framework 3.5 and 4.8 for Windows 10 Version 1809 for x64 (KB5049615)	windows10.0-kb5049615-x64-ndp48_17bbac9f33539f6515297a7e2183d20b3b165424.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2024/12/windows10.0-kb5049615-x64-ndp48_17bbac9f33539f6515297a7e2183d20b3b165424.msu
KB890830_v5.131	n/a	Windows Malicious Software Removal Tool x64 - v5.131 (KB890830)	windows-kb890830-x64-v5.131.exe	https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/uprl/2025/01/windows-kb890830-x64-v5.131_b091e745124ba77a02629e887324f4802dc1e919.exe
KB4052623_4.18.24090.11	n/a	Update for Microsoft Defender Antivirus antimalware platform - KB4052623 (Version 4.18.24090.11) - Current Channel (Broad)	updateplatform.exe	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/defu/2024/10/updateplatfo rm.amd64fre_d3f6f8300855e56b8ed00da6dac55a3c4cbf8c20.exe



LEGAL MANUFACTURER

CANON MEDICAL SYSTEMS CORPORATION

1385, SHIMOISHIGAMI, OTAWARA-SHI, TOCHIGI 324-8550, JAPAN